



ferrum

FERRUM IN AMMONIUM SULFATE PRODUCTION FAST AND PROFESSIONAL REPAIR

For a nitrogen fertilizer manufacturer in Europe, Ferrum successfully supported the time-critical repair of a P-80/2 pusher centrifuge. Thanks to precise planning and close coordination, the unit was restored reliably and on schedule.



”

We would like to thank David Koch for his high professional competence and responsibility during the repair of the pusher centrifuge P-80/2 in our ammonium sulfate plant. The repair was carried out at the highest qualitative level and within the required time. We greatly appreciated the fast and reliable support provided by Ferrum throughout the entire process.

Nitrogen fertilizer manufacturer, Europe



Ferrum Process Systems Ltd. | Industriestrasse 11
5503 Schafisheim | Switzerland | T +41 62 889 14 11
centrifuges@ferrum.net | ferrum.net



CONTACT US

prch.sales@ferrum.net